INTEGRATED VISUAL DATA TECHNOLOGY INC.
Solutions that lift your business

# Operator Usage Guide

SkidWeigh Plus ED3-Zebra V1.0

**LCD Display**

When LCD display shows a load weight press **"P"** key to get barcode label with load weight information




## ED3-Zebra SkidWeigh Plus

Turn on ignition switch on
The LCD display will show date / time.
Wait until Bluetooth icon is shown on LCD display. System is ready to operate.






### Insert the forks into the pallet or product to be weighed

- Lower the loaded forks to the ground.
- With LCD showing date/time, lift load **just above the ground**
- Do not manipulate the tilt, side shifter or move vehicle
- LCD display will show "PLEASE WAIT".
- Within few seconds load weight will be indicated on LCD display.
  If you press **"P key"** the barcode ticket will be provided on Zebra printer



**Note: LCD display must show date / time to initiate weighing cycle!**
**Loaded forks must be on the ground!**




Mounting brackets with vibration mounts

**Bluetooth Icon**

**"Enter key"**

Scroll keys

Function key

**With LCD showing load weight press "P" key and barcode label with data will be provided**

No. ID-R3AT5F
350 Labels
Size: 3" x 1.75"








Latch Release Button For Media Load

